Government of Kerala
1974

Reg. No. K. 97.

KERALA GAZETTE

EXTRAORDINARY

PUBLISHED BY AUTHORITY

Vol. XIX] Trivandrum, Friday, 29th November 1974 / 8th Agrahayana 1896 [No. 807

GOVERNMENT OF KERALA

Water & Power (Inter State Waters) Department

NOTIFICATION

G. O. MS. 51/74/W&P. *Dated, Trivandrum, 29th November 1974.*

S. R. O. No. 864/74.—In exercise of the powers conferred by section 1 of the Madras Irrigation Cess Act, 1865 (Madras Act VII of 1865) and in supersession of all previous Notifications on the subject, the Government of Kerala hereby make the following rules, for the levy of water cess in respect of crops raised by the ryots on lands with the aid of water from Shiriya Anicut, Bombrana Anicut, SWE Anicut across Uppala river, SWE dam across Mogral river, Karattuvayal Lift Irrigation scheme and the Minor Irrigation works constructed or old works repaired at Government cost in Kasargode and Hosdurg taluks of Cannanore District specified in the appendix to this Notification, the same having been previously published as required by section 3 of the Madras Irrigation Cess (Amendment) Act, 1900 (Madras Act V of 1900), namely:—

RULES

In respect of crops raised by the ryots on lands with the aid of water from the Shiriya anicut, Bombrana anicut, S.W.E. anicut across Uppala river, S.W.E. dam across Mogral river, Karattuvayal lift

Irrigation scheme and the Minor Irrigation works constructed or old works repaired at Government cost in Kasargode and Hosdurg taluks of Cannanore District, specified in the Appendix to this notification, water cess shall be levied with effect on and from the 1st July, 1974, at the following rates, namely:—

Name of Irrigation Works	*Particulars of crops*	*Rate of water cess per hectare*
(1)	(2)	(3)
		Rs.
1. Shiriya Anicut 2. Bombrana Anicut 3. S.W.E. Anicut across Uppala river in Uppala village 4. S.W.E. Dam across Mogral river at Kotakunje in Mogral Puthur village	(i) Lands already registered as single crop wet lands and on which two paddy crops could be raised	62
	(ii) lands already registered as single crop wet lands and on which more than two paddy crops could be raised	99
	(iii) Other lands already registered as wet lands and on which two paddy crops could be raised	62
	(iv) other lands already registered as wet lands and on which more than two paddy crops could be raised	99
	(v) lands made fit for cultivation and on which only one paddy crop could be raised	37
	(vi) lands made fit for cultivation and on which two paddy crops could be raised	62
	(vii) lands made fit for cultivation and on which. more than two paddy crops could be raised	99
	(viii) other lands benefited	62

(1)	(2)	(3)
		Rs.
5. Karattuvayal lift Irrigation scheme	(i) lands already registered as single crop wet lands and on which two paddy crops could be raised	at 50 % more of the rates specified in respect of items 1-4
	(ii) lands already registered as single crop wet lands and on which more than two paddy crops could be raised	
	(iii) other lands already registered as wet lands and on which two paddy crops could be raised	
	(iv) other lands already registered as wet lands and on which more than two paddy crops could be raised	
	(v) lands made fit for cultivation and on which only one paddy crop could be raised	
	(vi) lands made fit for cultivation and on which two paddy crops could be raised	
	(vii) lands made fit for cultivation and on which more than two paddy crops could be raised	
	(viii) Other lands benefited	
6. Minor Irrigation works constructed or old works repaired at Government cost, specified in the Appendix		17

By order of the Governor

V. U. K. Nambissan,

Joint Secretary to Government

APPENDIX

List of Minor Irrigation Works

Kasargode Taluk

1. Improvements to Omanjoor tank in Bangramanjeshwar village.
2. Dam at Kuriadkabail in Paivalike village.
3. Katta at Hosanbail thodu in Pathur village.
4. Katta at Bakrabail thodu in Pathur village.
5. Katta at Payyathabail in Pathur village.
6. Katta at Chedi in Moodambail village.
7. Katta at Kotikan in Mangalpady village.
8. Katta across Channel in R. S. No. 75|1 of Hosabettu village.
9. Katta at Deriya in Puthur village.
10. Katta at Kandoor in Moodambail village.
11. Bund at Thotta in Moodambail village.
12. Bund at Pajingar in Moodambail village.
13. Katta at Parekatta in Kodlamogaru village.
14. Bund at Kambattimaru in Paivalike village.
15. Katta at Noogikatta in Kodlamogaru village.
16. Dam at Uppalike in Maire village.
17. Bund across Kuriathodka in Kattukukke village.
18. Bund at Kudrekkatta in Kodlamogaru village.
19. Bund at Poyye in Vorkady village.
20. Bund at Ujarubail in Vorkady village.
21. Bund at Manippody in Meenja village.
22. Bund at Beedu in Kodlamogaru village.
23. Bund across Channel in R. S. No. 49 of Bangramanjeshwar village.
24. Deepening of Idithodu in Mogral village.
25. Bund at Sevalu thodu in Vorkady village.
26. Bund at Amery in Chippar village.
27. Bund and deepening channel in Arikady village.
28. Bund at Konibail in Kodlamogaru village.
29. Widening and deepening Soormathodu in Hosabettu village.
30. Widening and deepening Paivalike thodu in Paivalike village.
31. S.W.E. Dam at Bangra Manjeswar village.
32. S.W.E. Dam in R. S. 76|3 of Hosbettu village.
33. Vented dam across Kadambara thodu in Kadambar village.
34. Flood bund near the cross bar at Odanchal in Muliar village.
35. Deepening poinachi thodu in Thekkil village.
36. Deepening and desilting Paramba thodu in Thekkil village.
37. Flood prevention bund on the left bank of Kalalthodu in Paivalike village.
38. Deepening and widening the channel flowing behind the railway Goods shed Majeshwar in Udayar village.
39. Deepening and widening Sastikala thodu in Hosabettu village.
40. Flood prevention bund on the right bank of Kalalthodu in Paivalike village.

41. Vented dam at Iloige thodu in Pavoor village.
42. Cross bar across Alampady thodu In Muttathody village.
43. Tank at Peruvodi in Bayar village.
44. Deepening and widening Moorthodu in Bombrana village.
45. Deepening and widening Mulinja channel from Majalu to Mahalingeswar temple in Muliyar village.
46. Deepening and widening Kodibail channel from Sonkak to Kodibail katta in Kodibail village.
47. Cross bar across Shiriya kudlu thodu at Kalyanikatta in Kudlu village.
48. Improving Binachi tank in Muliyar village.
49. Cross bar across Kudal thodu in Muliyar village.
50. Flood prevention bund in Bekur village.
51. Deepening and widening Puthariadka thodu in Thekkil village.
52. Two vented cross bar at Deyyanthodu in Muliyar village.
53. Vented dam across Mallan Kottachal in Muliyar village.
54. Deepening and widening Perumbala thodu in Thekkil village.
55. Vented dam across Madarikatta in Heroor village.
56. S.W.E. cross bar across Kanchikatta thodu in Arikady village.
57. S.W.E. cross bar across Chullithimaru in Arikady village.
58. Flood prevention bund in Kodibail village.
59. Improvements to Machipuram tank in Thekkil village.
60. Improving Aryalkulam in Puthur village.
61. Improving Perambakkam tank in Perumbala village.
62. Improving Paikathimoru tank in Shiribagilu village.
63. Flood prevention bund at Ubarle branch I in Kubanoor village.
64. Flood prevention bund at Ubarle branch No. II in Kubanoor village.
65. Weir at Bevinje in Chengala village.
66. Flood prevention bund on the right bank of Kukkar stream in Mangalpady village.
67. S.W.E. bund across Kulmathodu in Puthur village.
68. Weir at Mykuzhikulam in Muliyar village.
69. Flood prevention bund in Ichlangod village.
70. Cross bar across Soovam thodu in Udiavar village.
71. Cross bar across Navoorthodu in Kannur village.
72. Improving in Thoukulam in Bedadka village.
73. Improving Kalarikulam tank in Madhur village.
74. S. W. E. Dam at Iddinthodu in Mogral village.
75. Flood prevention bund at Kallige in Meenja village.
76. Cross bar across Majakkor thodu in Muliyar village.
77. Desilting Thekkil valia thodu in Thekkil village.
78. Flood prevention bund in Kuloor village.
79. Flood prevention bund at Kallige branch No. II and III in Paivalike village.

80. Cross bar near Kallakotta road bridge in Adhur village.
81. Cross bar across Davatikeri in Bela village.
82. Improving Ujrekara tank in Puthur village.
83. Tank in R. S. No. 208|2 of Mangalpady village.
84. Cross bar across Kukkor thodu in Mangalpady village.
85. Improvement to the tank at Cherugoli in Mangalpady village.
86. Cross bar across Mogral river in Madhur village.
87. Vented cross bar at Bolakodu thodu in Pavoor village.
88. Cross bar across Bevinje thodu in Chengala village.
89. S.W.E. Dam Nellikunje in Kasargod.
90. Improving Sidibail tank in Kannur village.
91. Cross bar across Bellur thodu in Bellur village.
92. S.W.E. Dam at Madimogru thodu in Mogral village.
93. Improvement to the tank at Thottathodu in Kodibail village.
94. Deepening Kalanad thodu in Balnad village.
95. S.W.E. Dam across Kadavath in Puthur village.
96. Deepening Kalma thodu in Puthur village.
97. Desilting and deepening Kokodu thodu in Thalangara village.
98. Cross bar across Kotikar thodu in Koipady village.
99. Tank in R. S. No. 139|8 of Paivalike village.
100. Cross bar across Mogral river in Padi village.
101. S.W.E. Dam at Kalyet across Chemnad thodu in Chemnad village.
102. Tank at Goliadkam in Perumbala village.
103. Cross bar across Pallithody thodu in Katukukkee village.
104. Storage tank at Seetbagoli in Edned village.
105. Dam at Keduvanchil in Muliyar village.
106. Dam at Edneer in Pady village.
107. Cross bar at Perinadkam in Adhur village.
108. Cross bar across Karayal thodu at Kallanyudka in Karadka village.
109. Vented cross bar No. III of Kallaikatta in Kulur village.
110. Cross bar across Kudamanari thodu in Katukke village.
111. Cross bar across Enmakeje thodu in Enmakeje village.
112. Cross bar across Keveyoli thodu at Nankuzhikotta in Kudlu village.
113. Cross bar across Kovujoli thodu in R. S. No. 198|1 of Kudlu village.
114. Cross bar across Mognal river in Patla village.
115. Cross bar Deya thodu in Meenja village.
116. Flood bund at Kudalmerkala of Kudalmerkala village.
117. Cross bar across Adhur thodu at Sanjakadavu in Adoor village.
118. Cross bar across Sanyathodu in Enmakeje village.
119. Cross bar across Noondapallam in Padre village.
120. S.W.E. Dam at Suvarnagiri in Mangalpady village.
121. Tank at Surrada in Chippar village.
122. Vented dam at Uliya in Moodambail village.

123. Vented dam at Pampadakkatta in Chippaer village.
124. Cross bar at Kallakundam in Muliyar village.
125. Cross bar across Mogral river in Shirileagilu village.
126. Improvement to tank in R.S. 43|4 of Pathur village.
127. Improvement to Badriapatta tank in Enamakeje village.
128. A circular tank at Mundadou in Bela village.
129. Tank at Pulithadi in R.S. No. 102 of Kodibail village.
130. Cross bar across Karimbila thodu in kallakalya of Perdal village.
131. Cross bar across Karlaya thodu in Karadka village.
132. Cross bar across Muliyar thodu near road bridge in Muliyar village.
133. Forming a tank in Bekur village.
134. Cross bar across Chottakanam stream in Padi village.
135. Cross bar at Arotukadavu in Nekraje village.
136. Cross bar at Thayanoor in Chemnad village.
137. Tank at Panji in R.S. No. 302|2A in Mangalpady village.
138. Cross bar across Paichal in Kudlu village.
139. Excavating a tank at Edneer in pady village.
140. Vented cross bar near Bunts house across Perdal river, Perdal village.
141. Vented dam in R.S. 253 of Paivalike village.

Hosdurg taluk

1. Vented cross bar across Perloth stream, Ajanur.
2. Improvements to Madathu Kulam tank in N. Trikarpur.
3. Improvements to Kundukulam in Pilicode.
4. Deepening and widening of Timiri chal in Timiri.
5. Deepening and widening Kodakkat chal, in Pilicode. Kodakkat and Maniyat.
6. Improvements to Kodayakulam in Balla village.
7. Excavating tank at Chittari Palam in Chittari village.
8. Excavating Allappalli kulam in S. Trikarpur.
9. Cross bar across Paruthi puzha at Muttochira.
10. Deepening and widening Alanthitta Raman chira thodu in Kalayikode.
11. Renovating Kannankulam No. 1 in Timiri village.
12. Constructing a bar across Kanathil thodu at Kanam.
13. Excavating Eruvankulam tank in Kodoth village.
14. Constructing a vented cross bar across Thacharadikal across Peria thodu in Peria village.
15. Vented cross bar across Cherankadavu in E. Eleri village.
16. Excavating Tank at Kunnar kadu in S. Trikarpur village.
17. Constructing a vented bar across Barathodu at Kannamkulam in Pallikkara village.
18. Constructing a vented cross bar across Kalikadavu across Periya thodu in Periya.

19. Constructing a vented cross bar across Eravankara thodu at Thanoth.
20. Widening and deepening thodu from Mallakkara to Edapuzha.
21. Constructing a vented cross bar at Meengoth across Pullur stream.
22. Constructing a weir at Aramba in Belur village.
23. Constructing a cross bar across bar at Padikal Palayeri thodu in Padikal.
24. Constructing a cross bar across bar at Chamundikundu in Panathady village.
25. Constructing a cross bar at Attemala in Panathady village.
26. Deepening and widening thodu from Cherupuram to Nambiarkal.
27. Vented cross bar at Oliyathuchal in Cheemeni village.
28. Constructing a weir at Chittarikunnu in Panathady village.
29. Constructing a weir at Chamakuzhi chal.
30. Deepening and widening Cheriyachal Madiyanthode in Ajanur village.
31. Constructing a vented cross bar across Momanthodu in Pullur village.
32. Vented cross bar across Edapuzha Poovatty chal.
33. Constructing a vented cross bar at Periyathunthi in Panayal village.
34. Vented cross bar across Alanthatta Raman chira chal at Otakad.
35. Cross bar across Madikai river at Mundot.
36. Constructing a S.W.E. cross bar and protecting bund at Kallingal in Chittari village.
37. Excavating a tank in R. S. No. 330 of Cheruvathur village.
38. Constructing a weir at Koyhichal Panatherkavu in Panathady.
39. Constructing a vented cross bar across Timiri at Maliamkandam.
40. Constructing a weir at Kadayankayam.
41. Constructing a weir at Paladathu moola in Bare village.
42. Constructing a cross bar across Padikal Palayeri thodu at Vembally.
43. Improvements to Adambil tank.
44. Improvements to Mulana tank at Edamangavayal.
45. Constructing an anicut across Nafechal at Ramachira in Chiravathur village.

46. Vented cross bar across Madikai river at Kanayanchira in Madikai village.
47. S.W.E. anicut-cum-foot bridge across Nileshwar river at Nambiarkal.
48. Constructing the flow of Pullur stream and constructing 4 vented Dams across it.
49. Improvements to Kakkanam tank.
50. Improvements to Kavudeenkulam in Pilicode village.
51. Excavating tank at Karunnikulam in Timiri village.
52. Deepening and widening Thimiri chal in Cheruvathur village.
53. Improvements to Edakulam.
54. Cross bar at Kannankulam.
55. Improvements to Kulangara tank.
56. Improvements to Ambalakulam.
57. Improvements to Ayyankulam in Kodakkad village.
58. Desilting Thamarakulam and deepening thodu from Thamarakulam to Mundankandam.
59. Constructing a thodu at Pakkadam.
60. Constructing a tank at Palayivayal.
61. Mannampuram tank.
62. Noorja tank in Trikarpur.
63. Deepening Orvankara tank at Puthilot.
64. Renovation of Chavarikulam in Kodakkad village.
65. Deepening and widening Padikal Polerichal in Kodakkat village.
66. Excavating a tank at Adrikai in Udinoor village.
67. S.W.E. cross bar across Koovan puzha in Kaikot Kandam in south Trikarpur.
68. Salt water Exclusion bund between tank and river at Kadankot in Chervathur
69. S.W.E. cross bar across the Mundan Kandam in south Trikarpur village.
70. Improvement to Kunnathoor tank in Maniyat village.
71. Excavating tank at Palarikuzhiyil in Nileshwar village.
72. Anicut across Pathanchira in Cheemeni.
73. Vented dam across Chirakarakandi thodu.
74. S.W.E. cross bar across Beevicheri in South Trikarpur
75. Improvements to Eachikulam in Pilicode village.
76. S.W.E. cross bar at Chemmakara in Nileshwar village.
77. S.W.E. cross bar across Valiyaparamba thodu in Padnakadapuram.

78. Excavating tank at Puthilot in Kodakat village.
79. Weir across Chamkottachal at Kodankayan in Kinanur village.
80. On island scheme in Chervathur village.
81. Vented cross bar across Kuttatha thodu at Nhamikal in Chervathur village.
82. S.W.E. cross bar across Kookai thodu in Klayicode village.
83. Improvement to Vannathikulam in Uduma Panchayat.
84. Improvement to Poonchaol tank in Panayal village.
85. Cross bar across Madikai river at Pallathuvayal in Madikai.
86. Cross bar across Bare thodu at Karikkat.
87. Vented cross bar across Madikai river at Kakkat.
88. Constructing a weir cross Vannathichal at Kalingoth in Panayal village.
89. Improvements to Kodakkavayal tank in Timiri village.
90. Constructing a vented cross bar across Bare thodu in Cheerangode.
91. Constructing a vented cross bar across Nellikat thodu in Bella.
92. Improvement to Kavungal tank in Ajanur village.
93. Improvements to tank at Ramanagar in Ajanur village.
94. Constructing a SWE cross bar at Chathamath in Nileshwar.
95. Constructing a vented cross bar at Manadukan in Panathadi village.
96. Constructing a cross bar at Manhaganam in Pulloor village.
97. Constructing a salt water exclusion cross bar across Mundankandamchal at Thalachal.
98. Constructing a salt water exclusion Anicut across Padne river at Azhikkal.
99. Constructing a bridge-cum-vented cross bar across vellachal in Bare village.
100. Constructing a S.W.E. cross bar-cum-culvert across Kappil thodu at Kappil in Udma village.
101. Constructing a vented cross bar-cum-culvert at Kannanvayal in Panayal village.
102. Constructing a S.W.E. cross bar across Kavinchira chal at Kaithakad of Cheruvathur Panchayat.
103. Constructing a SWE cross bar at Madakara and Thaichimuad in Thuruthi of Cheruvathur Panchayat.

104. Constructing a cross bar across consmo thodu at Alungal in Puthur village.
105. Constructing a SWE cross bar and two bunds across Parathakai river in Nileshwar village.
106. Constructing SWE cross bar cum culvert at Annachal in Nileshwar village.
107. Constructing a vented cross bar across Koranthodu at Kayakodu in Madikai village.
108. Constructing a salt water exclusion cross bar at Pathikal in Thuruthi of Chervathur Panchayat.
109. Constructing a vented dam at Podippalam in Maloth Panchayat.
110. Constructing a weir at Nayar Kadavu in Maloth Panchayat.
111. Constructing a weir at Karimamvayal in Maloth Panchayat.
112. Constructing a vented cross bar-cum-bridge at Kalikadavu in Kanhangad Panchayat.
113. Constructing a vented cross bar-cum-bridge across Kalikadavu thodu in Bella village.
114. Constructing two bunds furrer S.W.E. cross bar across Podothirathi in Nileswar Panchayat.
115. Constructing a bridge cum vented cross bar across barathodu at Vellachal in Bare village.
116. Constructing a salt water exclusion cross bar across Cheriyachal.
117. Constructing a vented cross bar at Kolakachira in Panayal.
118. Constructing a salt water Exchira cross bar across Kuttichithodu.
119. Constructing a salt water exclusion cross bar at Kuthuthala in Turuthi of Cheruvathur Panchayat.
120. Construction of a vented dam and aqueduct at Ayampara in Periya village.
121. Excavating a tank in R.S. No. 222|1A Kodakat village.
122. Excavating a tank in Udinoor village.
123. Constructing a salt water exclusion cross bar across Kuttichi thodu in south Trikarpur village.
124. Constructing a salt water exclusion cross bar across Chiyachal in south Trikarpur.
125. Constructing a salt water exclusion cross bar at Kattutala in Thuruthy of Chervathur Panchayat.
126. Construction of a weir Mundamkandam in Panayat village.

127. Constructing a vented cross bar across Koranthodu at Kalyan in Madikai village.
128. Constructing a vented cross bar across Chirakkal thodu in Keekan village.
129. Deepening and widening Kalcharvattam tank in Belur Panchayat.
130. Deepening and widening Attanganam tank in Belur Panchayat.
131. Construction of a bridge cum vented cross bar at Para-kalingal in Belur Panchayat.
132. Improvements to tank in R.S. No. 49|3 of Klayikkode village of Cheemeni Panchayat.
133. Improvements to the tank in R.S. 31|11 of Klayicode village of Cheemeni Panchayat.
134. Constructing a S.W.E. cross bar across Keerithodu in Nileshwar Panchayat.
135. Construction of a vented cross bar across koran thodu at Madikai in Madikai village.
136. Construction of a S.W.E. cross bar across Nalamayil thodu at Nellikkal in Cheruvathur village.
137. Construction of a S.W.E. anicut at Kanai in Cheruvathur Panchayat.
138. Improvements to Kapukulam in Udinoor village.
139. Construction of a V.C.B. at Valamcherry in Pilicode village.
140. Construction of V.C.B. at Challankode in Kayyur village of Cheemeni Panchayat.
141. Construction of V.C.B. at Pattena across Pattena-Kayhuthemal thodu in Nileshwar Panchayat.

PRINTED AND PUBLISHED BY THE S. G. P. AT THE GOVERNMENT PRESS
TRIVANDRUM, 1974.

Government of Kerala
1974

Reg. No. K. 107.

KERALA GAZETTE

EXTRAORDINARY

PUBLISHED BY AUTHORITY

Vol. XIX] Trivandrum, Friday, 29th November 1974 / 8th Agrahayana 1896 [No. 805

NOTICE

No. C4-89329/74. *25th November* 1974.

Whereas I am satisfied that the public place mentioned in Schedule-I below is required in connection with the launching of the Equatorial Sounding Rockets from the Launching Station at Pallithura in the Attipra Village of Trivandrum Taluk by the Space Research Division of the Department of Atomic Energy to the Government of India.

I, V. N. Rajan, Inspector-General of Police in exercise of the powers conferred upon me under Section 24 of the Kerala Police Act, 1960 (Act V of 1961) hereby reserve temporarily the public place mentioned in Schedule-II and prohibit persons from entering the area so reserved save under conditions as may be prescribed by me.

Schedule I

PLACE OF LAUNCHING

The Rocket will be fired from the Launcher on a Pad at Pallithura near Trivandrum on the west coast of India.

FIRING SCHEDULE

Date	*Danger Time (I.S.T.)*	*Rocket type*	*Pay load*
25-11-1974 }			
26-11-1974 }	0000—0200 hrs.	M-100	Ionospheric
27-11-1974	0000—0200 hrs. and	M-100	Ionospheric
28-11-1974	1500—1700 hrs.	Menaka II	Met
29-11-1974 }			
30-11-1974 }	0000—0200 hrs.	M-100	Ionospheric
1-12-1974 }			

33/3679/G.

LAUNCHER CO-ORDINATES

Latitude	..	8° 32′ 34″ N
Longitude	..	76° 51′ 32″ E

FIRING DIRECTION

		M-100	Menaka-II
Azimuth (Effective)	..	235°	235°
Elevation (Effective)	..	82°	82°

Schedule—II

DANGER ZONES

1. A sector of radius 5 NM from launcher between azimuth angles 190° and 300°.

2. A sector of radii 15 NM and 50 NM from launcher between azimuth angles 220° and 260°.

All types of Aircraft, Shipping Boats etc., especially Fishing Boats of all description are warned to keep clear the Danger Zones mentioned above.

Office of the Inspector-General
of Police, Kerala State,
Trivandrum-10.

V. N. RAJAN,
Inspector-General of Police.

PRINTED AND PUBLISHED BY THE S. G. P. AT THE GOVERNMENT PRESS,
TRIVANDRUM, 1974.